



Glandore Harbour Yacht Club

SN 01/2020 SAFETY NOTICE

Algae build up on steps leading to GHYC pontoon.

All GHYC staff, members and volunteers should urge caution when utilising the steps leading onto the pontoon due to a build up of algae. The surface condition of the concrete steps is extremely slippery when wet. The handrail should always be used when ascending or descending to and from the pontoon.



Safety - It's Everyone's Business

Issued by: H&S representative

Issue date: 03.July.2020

FAO: all GHYC staff, members & volunteers